(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks	
No corre	ctions this week							09/04
Delete	Bournes Pond Aids maintained from May 15 to 0	Oct. 15.						
15000	- Buoy 1						Remove from list.	08/04
15005	- Buoy 2						Remove from list	08/04
15010	- Buoy 3						Remove from list	08/04
15015	- Buoy 4						Remove from list	08/04
15020	- Buoy 5						Remove from list	08/04
15025	- Buoy 6						Remove from list.	08/04
No corre	ctions this week							07/04
PENOBS	SCOT RIVER (Chart 13309)							
*	West Penobscot Bay							
4428 *	Kelly's Cove Aquaculture Buoy A *	44 22 17 N 068 57 04 W *	*	*	*	White and orange buoy marking aquaculture rafts.	Private aid.	06/04
4429	Kelly's Cove Aquaculture Buoy B	44 22 11 N 068 57 03 W	,			White and orange buoy marking aquaculture rafts.	Private aid	
*	*	*	*	*	*	*	*	06/04
4431 *	Kelly's Cove Aquaculture Buoy C *	44 22 11 N 068 57 01 W *	*	*	*	White and orange buoy marking aquaculture rafts.	Private aid.	06/04
4432	Kelly"s Cove Aquaculture Buoy D	44 22 17 N 068 57 03 W	,			White and orange buoy marking aquaculture rafts.	Private aid.	
*	*	*	*	*	*	*	*	06/04
4433	Kelly's Cove Aquaculture Lighted Buoy E	44 22 14 N 068 57 03 W	•		4	White and orange buoy marking aquaculture rafts.	Private aid.	
*	*	*	*	*	*	*	*	06/04
4434	Kelly's Cove Aquaculture Lighted Buoy F	44 22 13 N 068 57 03 W	•		4	White and orange buoy. Marks aquaculture.	Private aid.	
*	*	*	*	*	*	*	*	06/04
14685	Collier Ledge Lighted Isolated Danger Buoy DCL	41-35-44N 70-21-06W	Fl (2) W 5s		3	Black and red bands with (2) black spherical topmarks.	Replaced by can when endangered by ice.	
			*					06/04
14685	Collier Ledge Lighted Isolated Danger Buoy DCL	41-35-44N 70-21-06W	Fl (2+1) R 6s		3	Black and red bands with (2) black spherical topmarks.	Replaced by can when endangered by ice.	
	*					*	*	05/04
28040	- Lighted Buoy 7 At north edge of flats.	41-06-34N 72-19-20W *	Fl G 4s		4	Green.	Replaced by can from Nov. 15 to Apr. 15.	05/04
4580	Whitehead Light	43-58-43N 69-07-27W	Oc G 4s	75	6	Gray tower attached to red brick service room.	Emergency light of reducintensity when main light is extinguished. HORN: 2 blasts ev 30s	ed

4-Mar-04 Page 1

Summary of corrections to Volume I of the U.S. Coast Guard Light List for the 2003 edition.

(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks	
						41 *	(2s bl- 2s si- 2s bl- 24s si)	04/04
1575	- Buoy 16	44-35-59N 67-44-54W				Red nun.	Maintained from May 1 to Nov. 15.	03/04
4580	Whitehead Light	43-58-43N 69-07-27W	Oc G 4s	75	10	Gray tower attached to red brick service room.	Emergency light of reduce intensity when main light	d
						41	is extinguished. HORN: 2 blasts ev 30s (2s bl- 2s si- 2s bl- 24s si)	
							*	03/04
(Delete H 26190	leader) * - Narrows Channel Buoy CN13	40-58-13N 73-06-47W *				Green can.	Private aid.	03/04
(Delete H	Jandar)							03/04
`	- Narrows Channel Buoy CN14					Red nun.	Private aid.	03.04
37667	- Lighted Buoy 2	40-51-13N 73-56-48W	Fl R 2.5s	37	4	Red.	Replaced by LIB when endangered by ice.	
	*				*			02/04
37669	- Lighted Buoy 3	40-53-19N 73-55-39W	Fl G 2.5s	30		Green.	Replaced by LIB when	
	*				*		endangered by ice.	02/04
No corrections this week								

4-Mar-04 Page 2